<b>Work Orde</b> <i>May-13-13 1:02:</i>		1483		~ · · ·		Pa	ge 1						
Revision ID:	D3849-043 Aft Wearplate	: Assembly, STD Gear		Accept	*N900	<b>040</b>	100	)* :	Setup	Start Stop		S1 <sup>3</sup>	
Start Date: : : Required Date: : Reference:	5/07/13 5/31/13	Start Qty: 4.00 Req'd Qty: 4.00	*4* *4*		Cust Item I Customer:	D:							
Approvals:	Process Plan:QC:		Date: 13-05-/	✓ Tooling: SPC (Y/N):		ate:		1	Run Start Stop			R1 R2	
Sequence ID/ Work Center ID	)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stam	
Draw Nbr	Re	vision Nbr					-						
D3849	D												
110 *110* Large Fab Large Fab		Memo		0.00  0.00  hardcoat welding rod as p				×5		13-	06-0	13	MA

2059 B Hardcoat Welding Rod BATCH#: M/25/26

2- Weld D3901-1 bar to wearplate as per dwg D3849 304 S.S. Welding Rod BATCH #: 18 16 / 6 /

3- Transfer drill holes as per dwg

4- Cut excess bar material if necessary

120

Large Fab

QC9- Inspect visual per QSI004- Fusion Welds

Memo

0.00

\*120\* QC

Quality Control

0.00



												DQA.		ate.	
NCR:	Yes	/ No				WORK ORDER NON	-CO	NFORM	MANCE / UP	DATE	04	Closed:	n-	ate:	
,								1						ne.	
Work Ord	er:					DISPOSITION				AGAINST D	EPAF	RTMENT	/PROCESS		
	-					Rework			Skid-tube	Crosstube	7		Water Jet	:[	Engineering
Part !	No.					Scrap		1 (	Machining	Small Fab		Proc	d. Eng. Coor.	$\cdot$	Quality
						Use-as-is		1	noforming	Finishing		Rec/Stor	e/Packaging	_	Other
NCR I	No.					Work Order Update			Large Fab	Composite			Supplier	L	
Root					Descri	ption of work order update		Initial	Ac	tion	S	Sign &		-	
Cause		Date	Step	Qty		or Non-conformance	C	hief Eng	Desc	ription		Date	Verification	n_	QC Inspector
Doc/Data	Ш														
Equip/Tooling	Ш						}								
Operator	Ш														
Material	Ш														
Setup	Ш										1				
Other	Ш														
Process	Ш										1				
Supplier	Ш	1	1				i			•	1				
Training	Ш														
Unapproved															
							FAU	LT CATE	GORY						
Landi	ng C	Gear			<b>,</b>	General		_		_	_		•		,
	Ш	Bending				Bend	L	Grain		_	_	alized		L	Pressure/Forced
	Centre Not Concentric to O/S				o/s	BOM/Route	L	Hardwa	re	L		er/Under	tolerance		Temperature/Cure
1		Cracks				Broken/Damaged		Inspecti	on Incomplete		Par	t Incorrec	it .	$\perp$	Weld
		Crushed/	Crimped			Burrs	L	Instruct	ions Incomplete/	Unclear	Par	t Lost/Mi	ssing	lacksquare	Wrong Stock Pulled
		Cuffs				Contamination		Mainte	nance		Par	t Moved			
		Heat Trea	at			Countersink		Mislabe	led		Pos	sitioned W	/rong	_	-
l		Inspectio	n Strip in	Tube		Cut Too Short		Misread	1		Pov	wer Loss/S	Surge		Other

Out of Calibration

Out of Sequence

Outside Dimensions

Offset

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Inspection Strip in Tube

Torque Waves in Extrusion

Drill Holes

Drawing

Finish

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Quality Control

											DQA:	Date	:		
NCR:	Yes	/ No				WORK ORDER NON-	CON	IFORI	MANCE / UP	DATE	<b>0.4. 6</b> 5	D-4-			
									<del></del>		QA Closed:	Date	:		
Work Orde	er.					DISPOSITION				AGAINST DE	PARTMENT	/PROCESS			
Part N	Part No.  NCR No.  Root Cause Date Step Qty  oc/Data quip/Tooling perator				Rework Scrap Use-as-is Work Order Update  Rework Skid-tube Machining Thermoforming Large Fab			Machining noforming	Crosstube Small Fab Finishing Composite	nall Fab Prod. Eng. Coor. Qualitinishing Rec/Store/Packaging Othe					
Root					Descri	ption of work order update	Ti	nitial	Ac	tion	Sign &				
Cause		Date	Step	Qty	,	or Non-conformance	Ch	ief Eng	Desc	ription	Date	Verification	QC Inspector		
Doc/Data Equip/Tooling Operator Material Setup Other CU Process Supplier Training Unapproved													a Control of		
						<u> </u>	AUL	T CATE	GORY						
Landi		Bending Centre No	ot Concer	ntric to	o/s	General Bend BOM/Route		Grain Hardwa			Ovalized Over/Under	<del> </del>	Pressure/Forced Temperature/Cure Weld		
1		Cracks			1	Broken/Damaged	1 1	unspect	ion Incomplete		Part Incorred	LL I	IVVEIO		

Instructions Incomplete/Unclear

Maintenance

Out of Calibration

Out of Sequence

Outside Dimensions

Mislabeled

Misread

Offset

Wrong Stock Pulled

Other

Part Lost/Missing

Positioned Wrong

Power Loss/Surge

Part Moved

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Ripples in Bend

Turning Sequence

Wave/Twist in Tube

Crushed/Crimped

Inspection Strip in Tube

Torque Waves in Extrusion

Cuffs

Heat Treat

Burrs

Contamination

Countersink

Cut Too Short

Drill Holes

Drawing

Finish

Work Ordo May-13-13 1:02	er ID 10148 2:48 PM	33		*101	483*				Page 3
Item ID: Revision ID:	D3849-043		The second section of the second section of the second section of the second section s	Accept	*N90004	.0100	* Setup	Start	*NS1*
Item Name: Start Date: Required Date:		eart Qty: 4.00 eq'd Qty: 4.00	*4* *4*		Cust Item ID: Customer:			Stop	*NS2*
Approvals:			Date:	Tooling: SPC (Y/N):	Date:	· · · · · · · · · · · · · · · · · · ·	Run	Start Stop	*NR1* *NR2*
Sequence ID/ Work Center II	D De	peration escription entify as per dwg & Stoo	k Location: <u>FP-</u> OC	Set Up/ Run Hours  7 0.00	Tool ID Too	Code	Qty Qt	•	Reject Insp. Number Stamp
*160* Packaging Packaging		Memo		0.00			X5	<b>\$_</b>	<u> </u>
170	Qo	C21- Final Inspection - \	Work Order Release	0.00			_		Maria!
*17 <b>0</b> *		Memo		0.00			MUJ	13	-06-07

Memo

Quality Control

										DQA:	Date:	
NCR: Y	es / No				WORK ORDER NON-	CONI	FORN	/IANCE / UPDAT	re .	QA Closed:	Date:	
				<del>.</del>	DISPOSITION	T			AGAINST DE			
Work Orde	r:					_				, AKTIVILIVI,		
Part N	o				Rework Scrap Use-as-is		ı	Machining S	rosstube Small Fab Finishing	4	Water Jet d. Eng. Coor re/Packaging	Engineering Quality Other
NCR N	0				Work Order Update	]		<u> </u>	omposite	inec/stor	Supplier	
Root	Order:  Part No.  NCR No.  Date Step Qty  Ita Date			Descr	iption of work order update	lni	itial	Action		Sign &		
Cause	Date	Step	Qty		or Non-conformance	Chie	f Eng	Descriptio	on	Date	Verification	QC Inspector
oc/Data quip/Tooling Derator Material etup Other Process upplier Training												
Inapproved		<u>i</u>			· •	ALUT	CATE	CORV				
Landin	g Gear	· . · · ·		<del></del>	General	AULI	CATE	30K1				
	Landing Gear  Bending Centre Not Concentric to O/S Cracks Crushed/Crimped Cuffs Heat Treat Inspection Strip in Tube Ripples in Bend				Bend BOM/Route Broken/Damaged Burrs Contamination Countersink Cut Too Short Drill Holes Drawing	H	nstructi Mainte Mislabe Misread Offset	on Incomplete ions Incomplete/Uncle nance led	ear	Ovalized Over/Under Part Incorred Part Lost/Mi Part Moved Positioned W Power Loss/	ct ssing Vrong	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled Other
	Turning Sequence Finish				Finish	I lo	of S	equence				

Outside Dimensions

Wave/Twist in Tube

Page 1

Work Order ID:

101483

Parent Item:

D3849-043

Parent Item Name:

Aft Wearplate Assembly, STD Gear

**Start Date:** 5/07/13

Required Date: 5/31/13

Start Qty: 4.00

Required Qty: 4.00

**Comments:** 

IPP RevA: New issue DD verified by:EC DWG REV D DD VERF:ILM

IPP Rev:B 12.09.11 AS PER

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3849-3 Plate		Manufactured	No			110	Each	4.0000	<u>l</u> .	4	± . 4 1		
<b>5</b> 711				<b>Location</b>		Loc Qty	<u>L</u>	oc Code	_		17 00		
B 100974(x	5)			WA001		4			_×5		13-06-	03	MAL
	<i>J</i> 3			8267	3	2							
				9305	0	2							
<b>D3901-3</b> Bar		Manufactured	No			110	Each	14.0000	2	8	an eran ander after after after after	7B. 12.12.12	
	<del>~</del> \			<b>Location</b>		Loc Qty	L	oc Code					
B_10-16-86 &1	(0). }			WA001		14			_X	10	13-0	1//	z m
				9840	16	4					. / 6	16-0	1 111
				9915	0	10							

											DQA:	Date:	
NCR:	Yes	/ No				WORK ORDER NON-	COI	NFORI	MANCE / UPDATE			_	
· · ·									" " <u></u>		QA Closed:	Date:	
Work Orde	në.					DISPOSITION			AG	AINST DE	PARTMENT	/PROCESS	
WOIK OIG	-					Rework	1		Skid-tube Cros	stube	1	Water Jet	Engineering
Part N	VΩ					Scrap	ĺ	l ,	<b></b>	ill Fab	Pro	d. Eng. Coor.	Quality
10.00	-		<del>`</del>			Use-as-is	1	i	$\sim$ $\square$	ishing	4	re/Packaging	Other
NCR I	No.					Work Order Update	1		~ <del></del>	oosite		Supplier	1
											<b>4</b>		
Root					Descri	ption of work order update		Initial	Action		Sign &	:	
Cause		Date	Step	Qty		or Non-conformance	Cł	nief Eng	Description		Date	Verification	QC Inspector
Doc/Data	Ш						1						
Equip/Tooling	Ш					. •						•	,
Operator	Ш												
Material	Ш					•							
Setup	Ш						Ì			,			
Other	Ш										į		
Process	Н											,	•
Supplier	Н												
Training	Н											•	
Unapproved	Ш		1				A111	LT CATE	GORY		<u> </u>	L	
Landi	na G	Goar	<del></del>			General	<u> </u>	LICAIL	OOKI				
Landi		Bending				Bend	Г	Grain			Ovalized		Pressure/Forced
	-	Centre No	ot Conce	ntric to	o/s	BOM/Route	$\vdash$	Hardwa	re		Over/Under	tolerance	Temperature/Cure
	-	Cracks				Broken/Damaged	<b> </b>	4	ion Incomplete		Part Incorre	<del> </del>	Weld
	Н	Crushed/	Crimped			Burrs		-	ions Incomplete/Unclear		Part Lost/Mi	<u> </u>	Wrong Stock Pulled
	$\boldsymbol{\vdash}$	Cuffs	•			Contamination	Г	Mainte	•		Part Moved	-	_

Mislabeled

Out of Calibration

Out of Sequence

Outside Dimensions

Misread

Offset

Positioned Wrong

Power Loss/Surge

Other

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Heat Treat

Inspection Strip in Tube

Torque Waves in Extrusion

Countersink


Cut Too Short

Drill Holes

Drawing

Finish

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



С

REV. D

SCALE

NTS

SHEET 1 OF 10

DRAWING NO. D3849

CHECKED

MFG. APPR.

APPROVED

DATE 12.08.23

DE APPR.

8 7	6	5	4				3			2 .	1	1010
				ITEM	QTY -041	QTY -043	QTY -045	QTY -047	P/N D	ESCRIPTION		
	0			1	х				D3849-041 F	WD WEARPLATE ASSY, STD GE	AR	
	A A			2		х			D3849-043 A	FT WEARPLATE ASSY, STD GEA	R	
				3			х			FT WEARPLATE ASSY, FLOAT G		
				4						WD WEARPLATE ASSY, FLOAT (		
				11	1				D3849-1 P	LATE		
				12		1				LATE		
				13			1			LATE		
E O			•	14						LATE		
				15 16	1	2				AR AR		
<u>D3849-041 FWD V</u>	EARPLATE ASSY, STD	GEAR		17	<del>                                     </del>		2			AR		
		$\triangle$		21	A/R			A/R		ARDCOAT		
					A/R	A/R	A/R	A/R	4/14  PI	LUS ONE ROCKGUARD		
	D3849-043 AFT WEARP	LATE ASSY, STD GEA		SY, FL	OAT G	<b>SEAR</b>			·	2012	-09- 04 -09- 04	
A								RE	VISED FLAT PAT	FRN - CHANGED SLOT LOCATIONS	1	
	•						D	TO B6	MATCH 03901-1/	TERN - CHANGED SLOT LOCATIONS -3/-5 BARS (ZN B6-6, B3-6, B6-7, C2-7, 9).	DC	12.08.23
								RE	VISED FLAT PAT	FERN - CHANGE SLOT LOCATIONS	-	
		A	<u></u>				С	AD 04: (ZN RC	DED DOUBLE SLO 5. UPDATED DETA 1 B2-2). REMOVED CKGUARD COAT	TERN - CHANGE SLOT LOCATIONS. DTS AND D3901-3/-5 BARS ON -043/- NIL VIEWS. CHANGED WELD DETAILS D D3848-1/3-5/-7 GASKETS, ADD NG, REMOVE FINISH.	DC	12.08.21
	Q	0						RE	VISED FLAT PATT	ERN Ø0.375 WAS SLOT HOLE ON		
<u>a</u> . —	A						В	D3 A4 0.4 10) (ZN 87	049-17/-3F/-SF (ZN 849-047 (ZN D4-1, 9); ADD SECTION 4 WAS 0.438 (ZN , 1, ADD 0.88 & 0.44 1 A8-2, C6-2, C3-2 WAS 67.36 (ZN B4	FERN 00.375 WAS SLOT HOLE ON 1A4-5,84-7, 84-8, C2-10, 82-10, 1A0-0, A41-8,84-5, 80, 303849-7,7-2/N C49-9, A41-8,84-5, 80, 303849-7,7-2/N C49-9, N.K. (ZN C5-10), 0.88 WAS 0.875 & 33-10), ADD 0.25 & 0.88 (ZN D4-10, D3-2/N C3-10, & 80-3, 10), ADD FLAG NOTE A8-3, C6-3, C3-3, A8-4, C6-4, C2-4); 667)	RF	09.06.30
F.A.							A	NE	W ISSUE		RF	09.03.30
	D3849-0	047 FWD WEARPLATE	ASSY, FLOAT	GEAR			RE			DESCRIPTION	BY	DATE
							DES		RF	DART AEROSPAC	E USA,	INC.
							DRA		DC	KENT, WA		
							CHE	CKED	ALS.	DRAWING NO.		REV D